


## FLASH INFORMATION



SALES DIVISION  
NETWORK TECHNICAL INFORMATION

### FOX

**Subject:** WATER ENTERS THE CARBURETTOR THROUGH THE FLOAT BOWL VENT SYSTEM


**SUPERSEDES FLASH INFORMATION N° 37 DATED 03/2004**

**Problem:**

The engine misfires, back fires, or stalls due to water inside the carburettor's float bowl.

**After-sales service solution:**

Remove the carburettor and clean it.



Replace the original vent hose (1) with a shorter hose (2) **P/N: 752409**

**Note:** those machines which were serviced according to the method mentioned in flash information N° 37 of 03/2004 shall also be serviced and upgraded in accordance with this recommendation.

**Change in mass-production:**

In mass-production the vent hose is replaced with a shorter hose (like the one used on scooters).

From frame N°: VGAT1AAAL00202832 (Fox6APX)

**Time required for servicing:** 0.50h – Labour Code: 1900

	Dealership	Spare part	Mechanic 1	Mechanic 2	Mechanic 3
Signature					